

Underwriters Laboratories (UL LLC) Safety Certification (Manufacturing Factory) Report



Model: GMPU18x-y (x can be B, U, or UI; -y can be -1 to -8 or -1-1)

Manufacturing Facility(ies): Same as Applicant

Applicant: ELJINTEK, INC.
6th FL-1, 286-3 Shin-Ya Rd, Chien-Chen
Kaohsiung, 806 Taiwan
E246367

Listee: Same as Applicant
Listee File No.:

Report No.: E246367-D1009-1/A0/C0

Report (Re)Issue Date: 2023-12-12

Standard(s): ANSI/AAMI ES60601-1:2005, ES60601-1:2005/AMD1 1:2012, ES60601-1:2005/AMD2:2021, CAN/CSA-C22.2 No. 60601-1:08, CAN/CSA-C22.2 No. 60601-1:14 (including amendment 1) and Amendment 2:2022 (MOD) to CAN/CSA-C22.2 No. 60601-1:14

Additional Standards: None

Report Types: This report consists of the following report types:
[Yes] US Certification (UL Recognition)
[Yes] CAN Certification (cUL Recognition)

You are receiving this report as a Manufacturing Factory for the above-referenced Applicant.

This report covers the Safety evaluation of the referenced model(s) according to the standard(s) specified above.

This report includes portions of the full Applicant report and is designed to support any Follow-Up inspections at the Manufacture's facility.

Please refer to any Supplements to this document for a detailed manufacturer report, which includes information for the Follow-Up Inspection as specified below:

- **Appendix C:** Follow-Up Service Documentation
- **Appendix A:** Enclosures

Report Modifications Summary

The following changes were made to this report. If none listed in the below table, this report is the originally issued report.

NOTE: Some of the changes listed below were made in the full report and may not reflect the changes in this associated Factory Report, which just includes the Appendices listed above from the main report.

Date Modified (Year-Month-Day)	Modifications Made (include Report Reference Number)	Modified By
2023-12-12	New Issue - E246367-D1009-1/A0/C0	Stanley Chi / Johnny Lin